

Menu


HISTORY FILE MAP for year 2003-2004

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



001.06:07-06:16 10m RT data gap caused by 1-way to 2-way transition followed by BRC from 512bps to 1024bps at DSS54. No DR was raised.